


# MC2 Viewfinder Updates 8/7/24




- kV & mAs Gauges
- SID & SSD Gauges
- Perpendicularity
- Fuel Gauge Options
- Mode Switch Pop-up



# Viewfinder 3.2






# kV & mAs Gauges Option 1






Gauge changes based on the mode selection

## kV & mAs Gauges Option 2




Gauge changes based on the mode selection

# kV & mAs Gauges Option 3



Gauge changes based on the mode selection

# Mode Switch Popup




**Single  
Mode**







**DDR  
Mode**

**Fluoro  
Mode**

# Mode Change with kV & mAs Gauge adjustment





# Fuel Gauge







# Fuel Gauge





# SID/SSD




**SID Behavior**



# Tracking Option A




## Context





# Tracking Option B



Context



# Tracking Option C



Context

